




Surface Water Improvement in Silver Bow Creek AsDis during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek AsTR during Base Flow Conditions at SS-07 No Outliers




Surface Water Improvement in Silver Bow Creek CdDis during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek CdTR during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek CuDis during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek CuTR during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek CuDis during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek CuTR during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek FeDis during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek FeTR during Base Flow Conditions at SS-07 No Outliers




Surface Water Improvement in Silver Bow Creek HgDis during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek HgTR during Base Flow Conditions at SS-07




Surface Water Improvement in Silver Bow Creek PbDis during Base Flow Conditions at SS-07



Surface Water Improvement in Silver Bow Creek PbTR during Base Flow Conditions at SS-07



Surface Water Improvement in Silver Bow Creek ZnDis during Base Flow Conditions at SS-07



Surface Water Improvement in Silver Bow Creek ZnTR during Base Flow Conditions at SS-07

