




Notes:  
 1.) The user of this map is responsible for determining its suitability for his or her intended use or purpose. There is no guarantee for the accuracy of the material herein contained.  
 2.) Aerial Photography flown July 2011 for Atlantic Richfield Company, .25-foot resolution.

REV#	BY	DATE	FILE	DESCRIPTION
0	DRH	03-21-2012	REE.HIVE.E-GIS_ButtePrioritySoils@TL.Figure SW 17x11 Draft.mxd	
1	DRH	05-30-2014		Modified to remove H CC-0 2A & 02B stations



**DRAFT**

BUTTE PRIORITY SOILS  
TREATMENT LAGOON SITE MAP

FIGURE  
1